



Hot Work Permit Notice to All Contractors

A permit from the Dallas Fire-Rescue Department is required for all hot work. The 2007 Dallas Fire Code defines hot work as welding, cutting, Thermit welding, brazing, soldering, grinding, thermal spraying, thawing pipe, installation of torch-applied roof systems or any other similar work. The permit is \$80.00.

Permit applications must be obtained through the Fire Prevention, Education and Inspection Division before the work begins, and the permit shall be available for review at the job site during and for 48 hours after work has been completed. Before a permit will be given, all hot work equipment must be available for inspection by the Fire Prevention Officer.

For new construction job sites, call the scheduler Michelle Robinson at 214-671-9844 to schedule an appointment for a permit application and an inspection of equipment by a Fire Prevention Officer assigned to that job site. The general contractor shall require each of his contractors to have separate permits for their trades.

For all other sites, call the Fire Prevention Office at 214-670-4319 to schedule an appointment for a permit application and an inspection of equipment by a Fire Prevention Officer.

For safety tips on hot work, see "Checklist for Hot-Work" on the website: www.dallasfirerescue.com

8/24/07