



# Dallas Fire-Rescue News Release

RELEASE DATE		TIME	PUBLIC INFORMATION CONTACTS	
10 MARCH 2005		12 Noon	Lt. Joel Lavender <a href="mailto:jlavend@mail.ci.dallas.tx.us">jlavend@mail.ci.dallas.tx.us</a>	
ADDRESS		OCCUPANCY TYPE	Ph# 214-670-7949 Pager 214-670-4115 Pin # 9885	
3010 Fairview Ave.		Single Family		
STRUCTURAL LOSS	CONTENTS LOSS	TOTAL LOSS	CIVILIAN INJURIES	CIVILIAN FATALITIES
\$20,000	\$5,000	\$25,000		2
TOTAL FIREFIGHTERS	FIREFIGHTER INJURIES	FIREFIGHTER FATALITIES	TOTAL FIRE APPARATUS	
25	--	--	5	
TOTAL RESCUE AMBULANCES	TIME TO CONTROL INCIDENT	DISPLACED FAMILIES		
2	70 min	--		
ALARMS		INCIDENT CAUSE		
1 <sup>st</sup> Alarm 5:43 a.m., OutTapps @ 6:57 a.m.		Undetermined		
INCIDENT DESCRIPTION				
<p><b>Dallas Fire Inspectors Install Smoke Detectors in Owenwood Neighborhood</b></p> <p>Dallas Fire Inspectors are installing smoke detectors in the Owenwood neighborhood following Thursday mornings Fire Deaths. The first firefighters on the scene reported out with "a lot of smoke" and neighbors outside claiming that two people were trapped inside. Firefighter efforts to rescue the mother and daughter trapped inside the single- family dwelling were unsuccessful. Fire Investigators found a smoke detector inside of the house, but the batteries had been removed.</p>				